

CAPITAL RESTORATION

*St. Clement Catholic Church, Lakeview Neighborhood,
Chicago*



Fig 1. St. Clement Catholic Church.



Fig 2. Capital in the portico selected for sample stone repair.




Fig 3. Condition of the capital before repair.



Fig 4. First stage of salt neutralization.

CAPITAL RESTORATION

*St. Clement Catholic Church, Lakeview Neighborhood,
Chicago*





Fig. 5 Work in progress.



Fig. 6. Final touch up.



Before



After



CAPITAL RESTORATION

*St. Clement Catholic Church, Lakeview Neighborhood,
Chicago*

