

LIMESTONE RESTORATION

4601 North Beacon, Chicago Il



Fig 1. Before. This limestone portico was chemically cleaned to remove stains and discoloration.



Fig. 2 After. The stone was patched to restore it to its original appearance and repointed. Patching material – Heritage Limestone Restoration Mortar HL15

LIMESTONE RESTORATION

4601 North Beacon, Chicago Il



Figure 1: Before.



Figure 2: After.



Figure 3: Before.



Figure 4: After.



LIMESTONE RESTORATION

4601 North Beacon, Chicago Il

